

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲੋਂ

ਪ੍ਰਿੰਸੀਪਲ,
ਅਕਾਲ ਅਕੈਡਮੀ (ਪੰਜਾਬੀ ਮਾਧਿਅਮ),
ਚੀਮਾਂ, ਜਿਲ੍ਹਾ ਸੰਗਰੂਰ।

ਨੰਬਰ 568

ਮਿਤੀ 18-6-2024


ਵਿਸ਼ਾ: ਸਾਲ 2024-25 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ: ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ: AACPM/2024-25/15 ਮਿਤੀ 20-04-2024

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਰਾਹੀਂ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਲੋੜੀਂਦੀ
ਇੰਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ
ਜਾਂਦਾ ਹੈ ਜੀ। ਲੋੜੀਂਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 15000/- ਜੀ.ਆਰ ਨੰ: 675501 ਮਿਤੀ 18-6-24

ਰਾਂਹੀ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਨੱਥੀ / ਸਰਟੀਫਿਕੇਟ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ। 30

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ
ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਆਪ ਜੀ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ: 702 ਮਿਤੀ 25-04-2024 ਦੇ ਹਵਾਲੇ
ਵਿੱਚ ਸੂਚਨਾਂ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।


Part-II

Building Safety Report

Name of School: Akal Academy Cheema (Punjabi Medium), Tehsil Sunam, (Distt. Sangrur).

I have visited the above-mentioned School Building along with Sh. Shubham Goyal / Junior Engineer and on visually inspection; it seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building as per Drawings is 65350.21 Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **One Year, upto 31/03/2025**
- j) This Building Safety Certificate should not be considered as NOC for Road Access which will be taken separately by the School as per Government Policy No. 5/13/018-3BR3/1294287/3 Dated: 10.08.2018.


Sub Divisional Engineer
Provincial Sub Division PWD, B&R
Sangrur 